


# Special finish treatment on your turning tools



If you have CFM or other lathe machines, our special treatments....

1. Shave more cylinders than now
2. Get better surface roughness
3. Save much grinding time by stone



*Shed an old skin for timesaving*





# Checking the edge of diamond by \*SEM (x 500)

\*scanning electron microscope

